Field Service Bulletin No. 48

Order No.: DD+DIS256.01E

1 piece UST5K MA1

ADC Compact

Type 5145 / 100/101/140
Type 5145 / 200/201/240

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				X

Please file this document in section 13 of your technical documentation

New Hard Disk introduced

The new hard disk is only available in combination with the complete plug-in storage board (GS310).
Singular hard disks will not be delivered any longer.
For installation instructions, see Service Documentation (DD+DIS197.00E) Section 6.5 “Replacing a defective Hard Disk”.

Hard disk size: 4,1 GB
Order number: CM+9.5155.1540.1

Prerequisite for using the new hard disk is Software Version COP_1308.

If the software is not available on site you can download it from DigiNet.

printed in Germany 12 / 2001

AGFA